

IDP

## Test Report P-BA 138/2022e

## Determination of the Acoustic Performance of a Wastewater Installation System in the Laboratory according to DIN EN 14366

Institution for testing, supervision and certification, officially recognized by the building supervisory authority. Approvals of new building materials, components and types of construction

Director

Prof. Dr. Philip Leistner

**Client:** Fırat Plastik Kauçuk San. ve Tic. A.Ş.

Address: Türkoba Mah.Fırat Plastik Cad. No:23 Büyükçekmece İstanbul

TÜRKİYE

**Test object:** Wastewater system made of plastic "FIRAT RESIDENCE PIPE, 110x3.5, PVC-U,

06/06/22" with fittings "FIRAT DN 110, PVC-U" (manufacturer: Firat Plastik) and with acoustic pipe clamps with elastic inlay (double clamps) "FIRAT 4"",

110-115 with spacers 42 mm" (manufacturer: Firat Plastik).

**Content:** Results sheet 1: Summary of test results

Figures 1 to 3: Detailed results Figures 4 and 5: Test set-up

Annex A: Measurement set-up, noise excitation, acoustic

parameters

Annex F: Evaluation of measurements
Annex P: Description of the test facility
Annex V: Assessment according to VDI 4100

**Test date:** The measurement was carried out on August 9, 2022 in the test facilities of

the Fraunhofer Institute for Building Physics in Stuttgart.

Stuttgart, August 25, 2022

Responsible Test Engineer: Head of Laboratory:

Dipl.-Ing.(FH) J. Mohr M.BP. Dipl.-Ing.(FH) S. Öhler

The mentioned measuring results exclusively refer to the investigated test object. The test was carried out in a laboratory, accredited according to DIN EN ISO/IEC 17025:2018 by DAkkS. The accreditation certificate is D-PL-11140-11-01.

Any publication of this document in part is subject to written permission by the Fraunhofer Institute for Building Physics (IBP).



## Determination of the Acoustic Performance of a Wastewater Installation System in the Laboratory according to DIN EN 14366

P-BA 138/2022e

Results sheet 1

Client:

Fırat Plastik Kaucuk San. ve Tic. A.S.

Address: Türkoba Mah.Fırat Plastik Cad. No:23 Büyükçekmece İstanbul, TÜRKİYE

Test specimen:

Wastewater system made of plastic "FIRAT RESIDENCE PIPE, 110x3.5, PVC-U, 06/06/22" with fittings "FIRAT DN 110, PVC-U" (manufacturer: Firat Plastik) and with acoustic pipe clamps with elastic inlay (double clamps) "FIRAT 4"", 110-115 with spacers 42 mm" (manufacturer: Firat Plastik). Test object no.: S 11961-03; see figure 4 and 5.

Test set-up:

- The pipe system was mounted according to figure 4 and 5 (see also Annex A).
- The system consisted of wastewater pipes (nominal size OD 110), three inlet tees (~87°), two 45°-basement bends and a horizontal drain section. The inlet tees in the basement and in the ground floor were closed by lids supplied by the manufacturer.
  - <u>Pipe system:</u> "FIRAT RESIDENCE PIPE, 110x3.5, PVC-U, 06/06/22". Three layer pipes: Material PVC-U, wall thickness 3.7 mm, weight 2.42 kg/m, density 2.05 g/cm³, values measured by IBP. One-layer fittings: Material PVC-U, wall thickness 3.4 mm, density 1.85 g/cm³, values measured by IBP. Plug connection of the pipes and fittings (shaped pipe sockets).
  - <u>Pipe clamps:</u> Acoustic pipe clamps (double clamps) "FIRAT 4", 110-115, with spacers 42 mm" (manufacturer: Firat Plastik) with elastomer inlay (Shore-A 65). In every storey (EG and UG) respectively two clamps were installed. At the lower wall area one double clamp consisting of supporting clamp (with two elastomer spacer 2 x 21 mm on both sides) and fixing clamp was installed. At the upper wall area one loose clamp (with two elastomer spacer 2 x 21 mm on both sides) was mounted. To reduce contact to the pipe, the loose clamps and the supporting clamps were mounted with spacers (2 x 21 mm) between the locking tabs of both sides of the clamp. The clamps were closed with a tightening torque of 1 Nm for the supporting and loose clamps and with 2 Nm for the fixing clamps. The clamps were fixed to the installation wall with dowels and thread rods (figure 5).

The wastewater installation system was mounted by a technician under the authority of Fraunhofer IBP.

Test facility:

Installation test facility P12, mass per unit area of the installation wall: 220 kg/m², mass per unit area of the ceiling: 440 kg/m². Installation rooms: sub-basement (KG), basement (UG) front, ground floor (EG) front and top floor (DG), measuring rooms: UG front, UG rear (details in Annex P and DIN EN 14366: 2020-02)

Test method:

The measurements were performed according to DIN EN 14366:2020-02; noise excitation by steady water flow with 0.5 l/s, 1.0 l/s, 2.0 l/s and 4.0 l/s. Additional evaluation for comparison with requirements following German standards DIN 4109:2018-01 and VDI 4100:2012-10 (details in Annexes A, F and V).

Result:

	<u>Test specimen</u> : Wastewater system made of plastic "FIRAT RESIDENCE PIPE, 110x3.5, PVC-U, 06/06/22" with fittings "FIRAT DN 110, PVC-U" (manufacturer: Firat Plastik) and with acoustic pipe clamps with elastic inlay (double clamps) "FIRAT 4"", 110-115 with spacers 42 mm" (manufacturer: Firat Plastik).		Flow rate [l/s]			
			0.5	1.0	2.0	4.0
	Airborne sound pressure level L <sub>a,A</sub> [dB(A)] <b>according to DIN EN 14366</b> for the basement test-room	UG front	43	47	49	52
	Structure-borne sound characteristic level $L_{sc,A}$ [dB(A)] according to DIN EN 14366 for the basement test-room	UG rear	<10	<10	<10	11
	Installation sound level L <sub>AFeq,n</sub> [dB(A)] <b>following DIN 4109</b> in the basement test-room	UG front	43	47	49	52
		UG rear	<10	<10	10	15
	restallation sound level L <sub>AFeq,nT</sub> [dB(A)] <b>following VDI 4100</b> in the basement test-room	UG front	40	45	47	50
		UG rear	<10	<10	<10	11

Fraunhofer

FÖRDERUNG DE

**Test date:** August 9, 2022

Notes:

- For comparing test results with requirements according to DIN 4109 and VDI 4100 note Annex A.
- The above-mentioned measurement results require careful assembly of the pipe clamps (see test set-up).
- Sound levels below 10 dB(A) are not mentioned in the official test report, since they are subject to an increased measurement uncertainty and moreover are not noticeable in a normal living environment.



The test was carried out in a laboratory, accredited according to DIN EN ISO/IEC 17025:2018 by DAkkS. The accreditation certificate is D-PL-11140-11-01.

Stuttgart, August 25, 2022 Head of Laboratory:

